FORT EUSTIS, VA

MH 116

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work.
Duct not lined up and not level.
No duct plugs.



Tree planted in duct line.

MH 117

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.

Bldg 860

Two duct goes to the MH, one stubs out five feet.
Two duct go through the floor on one side of the Comm Rm and one on the other.







MH 33

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.





MH 33

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.





MH 35

A good manhole.

MH 92

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.
Collar not lined up with hole.



MH 92

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Local telco has installed poured splice-cases.
Core drills are to high and either point up or down.



MH 81

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.





MH 93

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.



MH 93

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.
Duct to close to the ceiling.



MH 26

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.

MH ?

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.

HH 29

Incorrect grounding,
Incorrect racks and racking,
Incorrect duct placement, and
Incorrect masonry work with slipped collar.
Duct not lined up and not level.
No duct plugs.

MH 0

This MH has been sitting this way for several months. They are waiting on a change to the contract to add four more duct into the DCO.

MH 0

Barrack Phase 2

Barracks Phase 2 and Swing Space